

## Tool List

The following equipment is required on the first day of class. Equipment must be in good working condition. Personal Protective Equipment (PPE) must be worn at all times in the welding lab. For your safety, you will not be allowed to participate in class without the proper equipment.

Description	Quantity	Approx. Cost
BLUE WELDING GLOVES	1	9.95
WELDMARK 9-13 VARI AUTO HELMENT	1	115.09
SAFETY GLASSES/CLEAR	1	1.69
NEMESIS IRUV 5.0 SAFETY GLASSES	1	9.26
REVCO BLACK DUFFLE BAG "22 LX12 "WX16"H	1	42.79
CC 1000-7 7/8 COMEAUX CAP	1	6.08
1/2"X12' E-Z READ POWERTAPE MEASURE	1	3.98
YS-50 MIG WELPER PLIERS	1	15.50
WY 400-1 FL HOLDER	1	1.31
F9-30C XL WLDG COAT FR 9OZ GREEN 30" LONG	1	19.30
SINGLE FLING LIGHTER	1	2.41
8" SLIP JOINT PLIERS	1	6.02
STEEL TOE BOOTS	1	100.00
<b>ESTIMATED TOTAL</b>		<b>333.38</b>